Oil Field Environmental Incident Summary

Responsible Party: SLAWSON EXPLORATION COMPANY, INC. **Well Operator:** SLAWSON EXPLORATION COMPANY, INC.

Well Name: MAGNUM 2-36-25H

Field Name: BAKER Well File #: 22249

Date Incident:3/24/2016Time Incident:10:30Facility ID Number:County:MCKENZIETwp:153Rng:101Sec:36Qtr:

Location Description: Open range, State land to the north

Submitted By: Ray Gorka Received By:

Contact Person: Ray Gorka

1675 BROADWAY STE 1600

DENVER, CO 80202

General Land Use: Other - Described Above Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:1.2 MileDistance Nearest Water Well:1.2 Mile

Type of Incident: Equipment Failure

Release Contained in Dike: No Reported to NRC: No

SpilledUnitsRecoveredUnitsFollowupUnits5Barrels5Barrels5barrels

Brine Other

Oil

Description of Other Released Contaminant:

.....

Inspected: Written Report Received: 12/30/2016 Clean Up Concluded: 3/30/2016

Risk Evaluation:

None.

Areal Extent:

About 20' X 20'

Potential Environmental Impacts:

No impact to surface or groundwater....

Action Taken or Planned:

Oil will be vacuumed, soaked up, grass off location to be mown, scrapped clean as per state inspectors.

Wastes Disposal Location: Indian Hills another licensed disposal facility.

Agencies Involved:

Updates

Date: 3/24/2016 Status: Reviewed - Follow-up Required Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release was not contained. Further follow-up necessary.

Date: 3/29/2016 Status: Inspection Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On location 3/29/2016 at 10:39 a.m. Release impacted area to the north off location. Staining was noticed on the grass and soil in an area approximately 40×50 ft. A soil sample was collected in area. Further follow-up is required.